RECEIVED
MAR 26 1996
NORTHERN REGION
IDWR

Form 238-7
8/95

IDAHO DEPARTMENT OF WATER RESOURCES

WELL DRILLER'S REPORT

Use Typewriter or Ballpoint Pen

097461

Office Use Only
Inspected by _____
Twp____ Rge____ Sec____
____1/4 ____1/4 ____1/4
Lat: : : Long: : :

1. DRILLING PERMIT NO. 97- 96- N- 0014 -____
Other IDWR No._____

2. OWNER:
Name Chris and Stephanie Clark
Address P.O.Box 869
City Priest River State ID Zip 83856

3. LOCATION OF WELL by legal description:
Sketch map location must agree with written location.

N / W / E / S — X

Twp. 56 North ☒ or South ☐
Rge. 05 East ☐ or West ☒
Sec. 11, ____ 10 acres 1/4 NE 40 acres 1/4 SE 160 acres 1/4
Gov't Lot ____ County Bonner
Lat: : : Long: : :
Address of Well Site 2.5 mi. N on Hwy 57 City Priest River
(Give at least name of road + Distance to Road or Landmark)

Lt._____ Blk._____ Sub. Name_____

4. USE:
☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other_____

5. TYPE OF WORK check all that apply (Replacement etc.)
☒ New Well ☐ Modify ☐ Abandonment ☐ Other_____

6. DRILL METHOD
☒ Air Rotary ☐ Cable ☐ Mud Rotary ☐ Other_____

7. SEALING PROCEDURES

SEAL/FILTER PACK Material	From	To	AMOUNT Sacks or Pounds	METHOD
Bentonite	0	19	3sacks	Overbore

Was drive shoe used? ☒ Y ☐ N Shoe Depth(s)_____
Was drive shoe seal tested? ☐ Y ☒ N How?_____

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
6"	+1	19	250	steel	☒	☐	☐	☐
					☐	☐	☐	☐
					☐	☐	☐	☐

Length of Headpipe_____ Length of Tailpipe_____

9. PERFORATIONS/SCREENS
☐ Perforations Method_____
☐ Screens Screen Type_____

From	To	Slot Size	Number	Diameter	Material	Casing	Liner
						☐	☐
						☐	☐
						☐	☐

10. STATIC WATER LEVEL OR ARTESIAN PRESSURE:
35 ft. below ground Artesian pressure _____ lb.
Depth flow encountered 149 ft. Describe access port or control devices:_____

NE SE 11 56N 5W

11. WELL TESTS:
☐ Pump ☐ Bailer ☒ Air ☐ Flowing Artesian

Yield gal./min.	Drawdown	Pumping Level	Time
5+gpm		175'	1 hr.

Water Temp. 51F Bottom hole temp._____
Water Quality test or comments: clear
Depth first Water Encountered 149'

12. LITHOLOGIC LOG: (Describe repairs or abandonment)

Bore Dia.	From	To	Remarks: Lithology, Water Quality & Temperature	Water Y	Water N
10	0	4	Sand & gravel		x
10	4	19	Granite/s&p/med		x
6	19	148	Granite/s&p/med		x
6	148	150	Granite/s&p/frac	x	
6	150	175	Granite/s&p/med		x

Completed Depth 175' (Measurable)
Date: Started 3-18-96 Completed 3-18-96

13. DRILLER'S CERTIFICATION
I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Firm Name Intermountain Drilling Firm No. 513
Firm Official_____ Date 3-19-96
and
Supervisor or Operator same Date_____
(Sign once if Firm Official & Operator)

FORWARD WHITE COPY TO WATER RESOURCES