

97-8137 EVIDENCE OF PRIORITY

BONNER COUNTY PARCEL DATA

Field	Value
ACRES	5.4
ADDRESS1	1261 W LIDDELL PL
ADDRESS2	
CITY	TUCSON
COUNTY	Bonner
ID	15672815
LEGAL1	8/9-58N-4W WILDWOOD SHORES LOT 5
LEGAL2	<null>
LEGAL3	<null>
LEGAL4	<null>
LEGAL5	<null>
LEGAL6	<null>
OWNER	SPLITT TRUST; SPLITT, CARL A & CORRINE TRUSTEES
P_ADDRESS	5653 GLEASON MC ABEE RD
P_ZIPCODE	83856
ParcelCount	1
PIN	RP005170000050A
SHAPE	Polygon
SOURCE	<null>
STATE	AZ
SUB_NAME	WILDWOOD SHORES
UPDATED	6/17/2023
YEAR_BUILT	2004
ZIPCODE	85704-3301

RECEIVED

JUN 28 1999

IDAHO DEPARTMENT OF WATER RESOURCES

WELL DRILLER'S REPORT

77180

Office Use Only
Inspected by _____
Twp _____ Rge _____ Sec _____
1/4 _____ 1/4 _____ 1/4 _____
Lat: _____ Long: _____

IDWR/North

1. WELL TAG NO. D 0005755

DRILLING PERMIT NO. 97-99-N-3

Other IDWR No. _____

2. OWNER:

Name Carl Splitt

Address 1261 W. Liddell

City Tucson

State AZ Zip 85704

3. LOCATION OF WELL by legal description:

Sketch map location must agree with written location.

North ☒ or South ☐
East ☐ or West ☒
Twp. 58 Rge. 04 Sec. 09
Gov't Lot _____ County Bonner
Lat: _____ Long: _____
Address of Well Site Gleason-McAbee
City Priest River

(Give at least name of road + Distance to Road or Landmark)

Lt. 05 Blk. _____ Sub. Name Wildwood Shores

4. USE:

☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other _____

5. TYPE OF WORK check all that apply (Replacement etc.)

☒ New Well ☐ Modify ☐ Abandonment ☐ Other _____

6. DRILL METHOD

☒ Air Rotary ☐ Cable ☐ Mud Rotary ☐ Other _____

7. SEALING PROCEDURES

SEAL/FILTER PACK	AMOUNT	METHOD
Material From To	Sacks or Pounds	
Bentonite 0 19	3sacks	Overbore

Was drive shoe used? ☒ ☐ N Shoe Depth(s) _____
Was drive shoe seal tested? ☐ Y ☐ N How? _____

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
6"	+1	99	250	steel	☒	☐	☒	☐

Length of Headpipe _____ Length of Tailpipe _____

9. PERFORATIONS/SCREENS

Perforations Method _____
Screens Screen Type Telescoping

From	To	Slot Size	Number	Diameter	Material	Casing	Liner
96	99	20		6"	stainless	☐	☐

10. STATIC WATER LEVEL OR ARTESIAN PRESSURE:

5 ft. below ground Artesian pressure _____ lb.
Depth flow encountered 95 ft. Describe access port or control devices: welded well cap

11. WELL TESTS:

☐ Pump ☐ Bailor ☒ Air ☐ Flowing Artesian

Yield gal./min.	Drawdown	Pumping Level	Time
35+		99	1 hr.

Water Temp. 51 Bottom hole temp. _____

Water Quality test or comments: clear

Depth first Water Encounter 95

12. LITHOLOGIC LOG: (Describe repairs or abandonment) Water

Bore Dia.	From	To	Remarks: Lithology, Water Quality & Temperature	Y	N
10	0	10	Clay		X
10	10	19	Sand & gravel		X
6	19	28	Sand & gravel		X
6	28	81	Clay w/sand lenses		X
6	81	91	Fine sand		X
6	91	99	Sand & gravel	X	

Completed Depth 99' (Measurable)
Date: Started 1-27-99 Completed 1-28-99

13. DRILLER'S CERTIFICATION

I/we certify that all minimum well construction standards were complied with at the time the rig was removed.

Company Name Inter Mountain Drig. Firm No. 513

Firm Official _____ Date 6-22-99

and _____

Driller or Operator _____ Date 6-22-99

(Sign once if Firm Official & Operator)

58N 4W 9

FORWARD WHITE COPY TO WATER RESOURCES