

IDAHO DEPARTMENT OF WATER RESOURCES WELL DRILLER'S REPORT

1 WELL TAG NO. D 0091046

Drilling Permit No 903815

Water right or injection well # _____

2 OWNER:

Name MICHAEL S. & ANN M. JACKSON

Address PO BOX 939

City PREST RIVER State ID Zip 83856

3 WELL LOCATION:

Sec 57 North ☒ or South ☐ Rge. 5 East ☐ or West ☒

Sec 17 1/4 SW 1/4 NW 1/4

County BONNER

Lot 48 0- 17.515' (Deg. and Decimal minutes)

Long -116 0- 59.7853' (Deg. and Decimal minutes)

Address of Well Site 2367 BEAR PAW RD.

City PREST RIVER

Blk _____ Sub Name _____

4 USE:

☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation ☐ Thermal ☐ Injection

☐ Other _____

5 TYPE OF WORK:

☒ New well ☐ Replacement well ☐ Modify existing well

☐ Abandonment ☐ Other _____

6 DRILL METHOD:

☒ Air Rotary ☐ Mud Rotary ☒ Cable ☐ Other _____

7 SEALING PROCEDURES:

Seal Material: BENTONITE From (ft) 0 To (ft) 38 Quantity (lbs or ft³) 1050 LBS Placement method/procedure OVERBORE

CHD DRY POUR

8 CASING/LINER:

Casing Liner Threaded Welded

From (ft) 0 To (ft) 224 Gauge or Schedule 250 Material STEEL

☒ ☐ ☐ ☒

☐ ☐ ☐ ☐

☐ ☐ ☐ ☐

☐ ☐ ☐ ☐

Has drive shoe used? ☒ Y ☐ N Shoe Depth(s) 224

PERFORATIONS/SCREENS:

Perforations ☐ Y ☒ N Method _____

Manufactured screen ☒ Y ☐ N Type STAINLESS STEEL

Method of installation SET ON BOTTOM, PULLED CASING

From (ft) 224 To (ft) 229 Slot size .016" Diameter (nominal) 5 Material STAINLESS Gauge or Schedule 250

Length of headpipe 5' Length of Tailpipe _____

Backer ☒ Y ☐ N Type K

9 FILTER PACK:

Filter Material _____ From (ft) _____ To (ft) _____ Quantity (lbs or ft³) _____ Placement method _____

10 FLOWING ARTESIAN:

Flowing Artesian? ☐ Y ☒ N Artesian Pressure (PSIG) _____

Escape control device _____

12. STATIC WATER LEVEL and WELL TESTS:

Depth first water encountered (ft) 190 Static water level (ft) 80

Water temp. (°F) COLD Bottom hole temp. (°F) COLD

Describe access port BOLT ON CAP

Well test: _____ Test method: _____

Drawdown (feet) _____ Discharge or yield (gpm) _____ Test duration (minutes) _____

100' 25+ 60

Pump ☐ Bailer ☒ Air ☐ Flowing artesian ☐

Water quality test or comments: GOOD

13. LITHOLOGIC LOG and/or repairs or abandonment:

Bore Dia. (in)	From (ft)	To (ft)	Remarks, lithology or description of repairs or abandonment, water temp.	Water	
				Y	N
10	0	1	TOP SOIL		X
	1	38	SILTY CLAY		X
8	38	40	" "		X
	40	122	WET SILTY CLAY		X
	122	186	HARDBAN CLAY		X
	186	190	WET SILTY CLAY		X
	190	219	SAND CLAY, WATER	X	
	219	244	SAND, WATER	X	

RECEIVED

FEB 22 2022

IDWR/NORTH

208-263-5974

Mark Pitts
Robin Pitts

Serving
North Idaho
Over 20 Years



DRILLING • PUMPS • WATER TREATMENT
Complete Systems • From the Well To The House

435 Woodview Rd. • Sandpoint, ID 83864

Completed Depth (Measurable) 244

Date Started 2/7/22 Date Completed 2/15/22

14. DRILLER'S CERTIFICATION:

I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Company Name AAA SWEETWATER DRILLING Co. No. 509

*Principal Driller Mark Pitts Date 2-17-22

*Driller [Signature] Date 2/17/22

*Operator II _____ Date _____

Operator I _____ Date _____

* Signature of Principal Driller and rig operator are required