

IDAHO DEPARTMENT OF WATER RESOURCES
WELL DRILLER'S REPORT

Office Use Only			
Well ID No.			
Inspected by			
Twp	Rge	Sec	
1/4	1/4	1/4	
Lat:	:	Long:	:

1. WELL TAG NO. D 0059397
DRILLING PERMIT NO. 861335
Water Right or Injection Well No. _____

2. OWNER:

Name Leonard Parks
Address 10034 Valley Home Ave
City Whittier State CA Zip 90603

3. LOCATION OF WELL by legal description:

You must provide address or Lot, Blk, Sub. or Directions to well.

Twp. 56 North ☒ or South ☐
Rge. 4 East ☐ or West ☒
Sec. 8 1/4 SW 1/4 NW 1/4
Gov't Lot _____ County Bonner

Lat: N48: 12: 841 Long: 116: 52: 144
Address of Well Site Sanborn Crk Rd
City Priest River

(Give at least name of road + Distance to Road or Landmark)

Lt. _____ Blk. _____ Sub. Name _____

4. USE:

☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other _____

5. TYPE OF WORK check all that apply (Replacement etc.)

☒ New Well ☐ Modify ☐ Abandonment ☐ Other _____

6. DRILL METHOD:

☒ Air Rotary ☐ Cable ☐ Mud Rotary ☐ Other _____

7. SEALING PROCEDURES

Seal Material	From	To	Weight / Volume	Seal Placement Method
bentonite	0	38	1300lbs	temp/casing

Was drive shoe used? ☒ Y ☐ N Shoe Depth(s) 75

Was drive shoe seal tested? ☐ Y ☒ N How? _____

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
6	+1 1/2	75	250	steel	☒	☐	☒	☐

Length of Headpipe _____ Length of Tailpipe _____

Packer ☐ Y ☒ N Type _____

9. PERFORATIONS/SCREENS PACKER TYPE

Perforation Method _____

Screen Type & Method of Installation _____

From	To	Slot Size	Number	Diameter	Material	Casing	Liner
						☐	☐
						☐	☐
						☐	☐

10. FILTER PACK

Filter Material	From	To	Weight / Volume	Placement Method

11. STATIC WATER LEVEL OR ARTESIAN PRESSURE:

80 ft. below ground Artesian pressure _____ lb.

Depth flow encountered _____ ft. Describe access port or control devices: _____

56N 04W 08

12. WELL TESTS:

☐ Pump ☐ Bailor ☒ Air ☐ Flowing Artesian

Yield gal./min.	Drawdown	Pumping Level	Time
2		400	1 1/2 hr

Water Temp. cold Bottom hole temp. _____

Water Quality test or comments: _____

Depth first Water Encounter 155

13. LITHOLOGIC LOG: (Describe repairs or abandonment)

Water

Bore Dia.	From	To	Remarks: Lithology, Water Quality & Temperature	Y	N
10	0	38	gravel large		
6	38	75	sand&gravel		
	75	155	black&white granite, broken seam@155-157	x	
	157	280	firm gray granite		
	280	400	black&white granite	x	

RECEIVED

JUL 11 2011

IDWR / NORTH

Completed Depth 400ft (Measurable)

Date: Started 6-16-11 Completed 6-21-11

14. DRILLER'S CERTIFICATION

I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Company Name Bronson Water Wells Firm No. 360

Principal Driller AD Brown Date 6/23/11

and Driller or Operator II _____ Date _____

Operator I _____ Date _____

Principal Driller and Rig Operator Required.
Operator I must have signature of Driller/Operator II.