

97-8009 EVIDENCE OF PRIORITY

BONNER COUNTY PARCEL DATA FROM 2016

Field	Value
ACRES	12
ADDRESS1	75 SHAW RD
ADDRESS2	
CITY	PRIEST RIVER
COUNTY	Bonner
ID	15712032
LEGAL1	18-56N-4W NE E OF EAST BRANCH RD CPWRS
LEGAL2	<null>
LEGAL3	<null>
LEGAL4	<null>
LEGAL5	<null>
LEGAL6	<null>
OWNER	BENTE, MICHAEL W & ROBIN
P_ADDRESS	75 SHAW RD
P_ZIPCODE	83856
ParcelCount	1
PIN	RP56N04W181800A
SHAPE	Polygon
SOURCE	<null>
STATE	ID
SUB_NAME	
UPDATED	6/17/2023
YEAR_BUILT	2001
ZIPCODE	83856

AERIAL IMAGERY SHOWING EVIDENCE OF 1 HOME – 2006



AERIAL IMAGERY FROM 2011 – SHOWING 2 HOMES



Form 238-7
30 AUG 07 1998

Office Use Only
Inspected by _____
Twp _____ Rge _____ Sec _____
_____ 1/4 _____ 1/4 _____ 1/4
Lat: : : Long: : :

1. DRILLING PERMIT NO. 97-98-N-0007
Other IDWR No. D0003718

2. OWNER:
Name John & Mary Carlson
Address P.O.Box 850
City Priest River State ID Zip 83856

Sketch map location must agree with written location.


 Twp. 56 North ☒ or South ☐
 Rge. 04 East ☐ or West ☐
 Sec. 18 1/4 SE 1/4 NE 1/4
10 acres 40 acres 160 acres
 Gov't Lot _____ County Bonner
 Lat: _____ Long: _____
 Address of Well Site Eastside Road
 City Priest River

Lt. _____ Blk. _____ Sub. Name _____

4. USE:
☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other _____

5. TYPE OF WORK check all that apply (Replacement etc.)
☒ New Well ☐ Modify ☐ Abandonment ☐ Other _____

6. DRILL METHOD
☒ Air Rotary ☐ Cable ☐ Mud Rotary ☐ Other _____

SEAL/FILTER PACK			AMOUNT	METHOD
Material	From	To	Sacks or Pounds	
Bentonite	0	19	3sacks	Overbore

Was drive shoe used? ☒ Y ☐ N Shoe Depth(s) _____
Was drive shoe seal tested? ☐ Y ☐ N How? _____

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
6"	+1	117	250	steel	☒	☐	☒	☐
					☐	☐	☐	☐
					☐	☐	☐	☐

Length of Headpipe _____ Length of Tailpipe _____

☐ Perforations Method _____
☒ Screens Screen Type **Telescoping**

From	To	Slot Size	Number	Diameter	Material	Casing	Liner
117	122	10		6"	stainless	☒	☐
						☐	☐
						☐	☐

89 ft. below ground Artesian pressure _____ lb.
Depth flow encountered 89 ft. Describe access port or
control devices: well cap

56 N 4 W 18

☐ Pump ☐ Bailer ☒ Air ☐ Flowing Artesian

Yield gal./min.	Drawdown	Pumping Level	Time
6gpm		122'	1 hr

Water Temp. 49 Bottom hole temp. _____

Water Quality test or comments: clear

Depth first Water Encountered 89'

Water

[illegible]

Completed Depth	122'	(Measurable)
Date: Started	7-14-98	Completed 7-14-98

I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Firm Name **Intermountain~~X~~ Drilling** Firm No. **513**

Firm Official [Signature] Date 8-6-98

and

Supervisor or Operator Jack Cook Date 8-6-98
(Sign once if Firm Official & Operator)

FORWARD WHITE COPY TO WATER RESOURCES