RECEIVED

Form 238-7
11/97 JUL 03 2000

IDAHO DEPARTMENT OF WATER RESOURCES
WELL DRILLER'S REPORT


Office Use Only
Inspected by _____
Twp ____ Rge ____ Sec ____
____ 1/4 ____ 1/4 ____ 1/4
Lat: : : Long: : :

IDWR/North 13319

1. WELL TAG NO. D _____
DRILLING PERMIT NO. ____-____-____-_____-_____
Other IDWR No. 764623

2. OWNER: BRAD PHILLIPS
Name _____
Address 6448 HWY 57
City PRIEST RIVER State ID Zip 83856

3. LOCATION OF WELL by legal description:
Sketch map location must agree with written location.



Twp. 57 North ☒ or South ☐
Rge. 5 East ☐ or West ☒
Sec. 26, SE 1/4 (10 acres) SE 1/4 (40 acres) NW 1/4 (160 acres)
Gov't Lot ____ County BONNER
Lat: : : Long: : :
Address of Well Site 6448 HWY 57
City PRIEST RIVER
(Give at least name of road + Distance to Road or Landmark)

Lt. _____ Blk. _____ Sub. Name _____

4. USE:
☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other _____

5. TYPE OF WORK check all that apply (Replacement etc.)
☒ New Well ☐ Modify ☐ Abandonment ☐ Other _____

6. DRILL METHOD
☒ Air Rotary ☒ Cable ☐ Mud Rotary ☐ Other _____

7. SEALING PROCEDURES

SEAL/FILTER PACK Material	From	To	AMOUNT Sacks or Pounds	METHOD
BENTONITE	0	18	350 LBS	TEMP CASE

Was drive shoe used? ☒ Y ☐ N Shoe Depth(s) 18
Was drive shoe seal tested? ☐ Y ☐ N How? _____

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
6	+2	18	.125	A53B	☒	☐	☒	☐
					☐	☐	☐	☐
					☐	☐	☐	☐

Length of Headpipe _____ Length of Tailpipe _____

9. PERFORATIONS/SCREENS
Perforations Method NO SCREEN
Screens Screen Type _____

From	To	Slot Size	Number	Diameter	Material	Casing	Liner
						☐	☐
						☐	☐
						☐	☐

10. STATIC WATER LEVEL OR ARTESIAN PRESSURE:
15 ft. below ground Artesian pressure _____ lb.
Depth flow encountered 31 ft. Describe access port or control devices: STEEL CAP

11. WELL TESTS:
☐ Pump ☐ Bailer ☒ Air ☐ Flowing Artesian

Yield gal./min.	Drawdown	Pumping Level	Time
25			

Water Temp. _____ Bottom hole temp. _____
Water Quality test or comments: LOW YIELD / CLEAR
Depth first Water Encounter 31

12. LITHOLOGIC LOG: (Describe repairs or abandonment)

Bore Dia.	From	To	Remarks: Lithology, Water Quality & Temperature	Water Y	Water N
8	0	1	BROWN DIRT		X
8	1	5	BROWN SANDY LOAM		X
8	5	18	HARD GREEN GRANITE		X
6	18	30	HARD GREEN GRANITE		X
6	30	31	FRACTURE	X	
6	31	150	HARD GREEN GRANITE		

Completed Depth 150 FEET (Measurable)
Date: Started MAY 29 00 Completed JUN 23 00

13. DRILLER'S CERTIFICATION
I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Company Name THE DRILLERMAN Firm No. 627

Firm Official _____ Date _____
and
Driller or Operator [signature] Date Jun 26 2000
(Sign once if Firm Official & Operator)

57N 5W 26

FORWARD WHITE COPY TO WATER RESOURCES