

IDAHO DEPARTMENT OF WATER RESOURCES
WELL DRILLER'S REPORT

Office Use Only			
Well ID No. _____			
Inspected by _____			
Twp _____	Rge _____	Sec _____	
_____ 1/4	_____ 1/4	_____ 1/4	
Lat: _____		Long: _____	

1. WELL TAG NO. D 0054108DRILLING PERMIT NO. 249474

Water Right or Injection Well No. _____

2. OWNERName Don BentonAddress 16313 NE Leaper RoadCity VancouverState WAZip 98686**3. LOCATION OF WELL by legal description:**

You must provide address or Lot, Blk, Sub. or Directions to well.

Twp. 58North ☒

or

South ☐Rge. 4East ☐

or

West ☒Sec. 22

1/4

NE

1/4

NE

1/4

10 acres

40 acres

160 acres

Gov't Lot _____

County Bonner

Lat: _____

Long: _____

Address of Well Site Eastside RoadCity Priest River

(Give at least name of road + Distance to Road or Landmark)

Lt. _____

Blk. _____

Sub. Name _____

4. USE:☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation☐ Thermal ☐ Injection ☐ Other _____**5. TYPE OF WORK** check all that apply

(Replacement etc.)

☒ New Well☐ Modify☐ Abandonment☐ Other _____**6. DRILL METHOD:**☒ Air Rotary☐ Cable☐ Mud Rotary☐ Other _____**7. SEALING PROCEDURES**

Seal Material	From	To	Weight / Volume	Seal Placement Method
Bentonite S	0	19	6 sack	Overbore

Was drive shoe used? ☒ Y ☐ N Shoe Depth(s) 185'Was drive shoe seal tested? ☐ Y ☒ N How? _____**8. CASING/LINER:**

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
6	+1	185	0.25	Steel	☒	☐	☒	☐

Length of Headpipe N/ALength of Tailpipe N/APacker ☐ Y ☒ NType N/A**9. PERFORATIONS/SCREENS PACKER TYPE**Perforation Method N/AScreen Type & Method of Installation N/A

From	To	Slot Size	Number	Diameter	Material	Casing	Liner
						☐	☐

10. FILTER PACK

Filter Material	From	To	Weight/Volume	Placement Method

11. STATIC WATER LEVEL OR ARTESIAN PRESSURE:145 ft. below groundArtesian pressure N/A lb.Depth flow encountered N/Aft. Describe access port or control devices: N/A**12. WELL TESTS:**☐ Pump☐ Bailer☒ Air☐ Flowing Artesian

Yield gal./min.	Drawdown	Pumping Level	Time
15-20		185'	1 hour

Water Temp. 50

Bottom hole temp. _____

Water Quality test or comments: ClearDepth first Water Encounter 182'**13. LITHOLOGIC LOG: (Describe repairs or abandonment)**

Water

Bore Dia.	From	To	Remarks: Lithology, Water Quality & Temperature	Y	N
10	0	19	Clay, gray		x
6	19	182	Clay, gray		x
6	182	185	Shale, broken	x	

RECEIVED

NOV 15 2007

IDWR/NOH

Completed Depth 185'

(Measurable)

Date: Started 10-03-07Completed 10-12-07**14. DRILLER'S CERTIFICATION**

I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Company Name Intermountain DrillingFirm No. 513Principal Driller Glen FrachhiseurDate 11-12-07

and

Driller or Operator II [Signature]Date 11-12-07

Operator I _____

Date _____

Principal Driller and Rig Operator Required.

Operator I must have signature of Driller/Operator II.

584 4W 22

FORWARD COPY TO WATER RESOURCES