

97-9662 – EVIDENCE OF PRIORITY
FROM BONNER COUNTY PARCEL DATA

Field	Value
ACRES	5.6
ADDRESS1	PO BOX 937
ADDRESS2	
CITY	PRIEST RIVER
COUNTY	Bonner
ID	15675690
LEGAL1	18-56N-4W VERDE FORESTA LOT 9 ESTATES CPWRS
LEGAL2	<null>
LEGAL3	<null>
LEGAL4	<null>
LEGAL5	<null>
LEGAL6	<null>
OWNER	DIXON, BRANDON & CASIE
P_ADDRESS	197 MOMORANTE LN
P_ZIPCODE	83856
PIN	RP027590000090A
SOURCE	<null>
STATE	ID
SUB_NAME	VERDE FORESTA ESTATES
UPDATED	6/17/2023
YEAR_BUILT	2019
ZIPCODE	83856-0937

IDAHO DEPARTMENT OF WATER RESOURCES WELL DRILLER'S REPORT

1. WELL TAG NO. D D0079513

Drilling Permit No. 725 889545

Water right or injection well # _____

2. OWNER: Brandon Dixon

Name Brandon Dixon

Address Po Box 937

City Priest River State ID Zip 83856

3. WELL LOCATION:

Twp. 56 North ☒ or South ☐ Rge. 04 East ☐ or West ☒
Sec. 18 1/4 1/4 1/4 1/4

Gov't Lot _____ County Bonner

Lat. 4812 194 (Deg. and Decimal minutes)

Long. 11653 368 (Deg. and Decimal minutes)

Address of Well Site 197 momoralte

City Priest River

Lot _____ Blk _____ Sub. Name _____

4. USE:

☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation ☐ Thermal ☐ Injection
☐ Other _____

5. TYPE OF WORK:

☒ New well ☐ Replacement well ☐ Modify existing well
☐ Abandonment ☐ Other _____

6. DRILL METHOD:

☒ Air Rotary ☐ Mud Rotary ☒ Cable ☐ Other _____

Seal material	From (ft)	To (ft)	Quantity (lbs or ft ³)	Placement method/procedure
benlonite	0	40	1250	pour

Diameter (nominal)	From (ft)	To (ft)	Gauge/ Schedule	Material	Casing Liner	Threaded	Welded
6"	+2	312	250	steel	☒	☐	☒
					☐	☐	☐
					☐	☐	☐
					☐	☐	☐

Was drive shoe used? ☒ Y ☐ N Shoe Depth(s) 312

9. PERFORATIONS/SCREENS:

Perforations ☐ Y ☒ N Method _____

Manufactured screen ☒ Y ☐ N Type Stainless Steel

Method of installation casing jacks

From (ft)	To (ft)	Slot size	Number/ft	Diameter (nominal)	Material	Gauge or Schedule
312	322	20	10	5"	SS	304

Length of Headpipe 2' Length of Tailpipe _____

Packer ☒ Y ☐ N Type K

Filter Material	From (ft)	To (ft)	Quantity (lbs or ft ³)	Placement method

11. FLOWING ARTESIAN:

Flowing Artesian? ☐ Y ☒ N Artesian Pressure (PSIG) _____

Describe control device _____

12. STATIC WATER LEVEL and WELL TESTS:

Depth first water encountered (ft) _____ Static water level (ft) 155

Water temp. (°F) cold Bottom hole temp. (°F) _____

Describe access port Well Cap

Well test:	Discharge or yield (gpm)	Test duration (minutes)	Pump	Boiler	Air	Flowing artesian
Drawdown (feet)	10+ gpm	2 hours	☒	☒	☐	☐

Water quality test or comments: good

13. LITHOLOGIC LOG and/or repairs or abandonment:

Bore Dia. (in)	From (ft)	To (ft)	Remarks, lithology or description of repairs or abandonment, water temp.	Water
10"	0	2	top soil	Y X
10"	2	40	course sand and gravel(some fine)	X
6"	40	55	fine brown sand	X
6"	55	122	blue clay	X
6"	122	182	blue clay some course sand	X
6"	182	202	cemented gravel hard	X
6"	202	222	blue clay	X
6"	222	302	blue clay sand layers some gravel	X
6"	302	322	course sand and gravel	X

RECEIVED

JUL 18 2019

IDWR/NORTH

Completed Depth (Measurable): _____
Date Started: 4.17.19 Date Completed: 5.20.19

14. DRILLER'S CERTIFICATION:

I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Company Name Pioneer Well Drilling Co. No. 725

*Principal Driller John McDaniel Date 5.20.19

*Driller John McDaniel Date _____

*Operator John McDaniel Date _____

Operator John McDaniel Date _____

* Signature of Principal Driller and rig operator are required.