RECEIVED
DEC 0 4 1997

Form 238-7
3/95

IDAHO DEPARTMENT OF WATER RESOURCES
POSTED
WELL DRILLER'S REPORT
Use Typewriter or Ballpoint Pen

Office Use Only
Inspected by _____
Twp ____ Rge ____ Sec ____
____1/4 ____1/4 ____1/4
Lat: : : Long: : :

NORTHERN REGION
IDWR

1. DRILLING PERMIT NO. 97.97.N.53 - 097765
Other IDWR No. D3416

2. OWNER:
Name Steve Yob
Address West 5315 Conestoga
City Spokane State WA Zip 99208

3. LOCATION OF WELL by legal description:
Sketch map location must agree with written location.

N / W / E / S

Twp. 59 North ☒ or South ☐
Rge. 4 East ☐ or West ☒
Sec. 10, ____ 10 acres 1/4 NE 40 acres 1/4 SW 160 acres 1/4
Gov't Lot 3 County Bonner
Lat: : : Long: : :
Address of Well Site Paul Street
City Coolin
(Give at least name of road + Distance to Road or Landmark)

Lt. ____ Blk. ____ Sub. Name ____

4. USE:
☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other ____

5. TYPE OF WORK check all that apply (Replacement etc.)
☒ New Well ☐ Modify ☐ Abandonment ☐ Other ____

6. DRILL METHOD
☒ Air Rotary ☐ Cable ☐ Mud Rotary ☐ Other ____

7. SEALING PROCEDURES

SEAL/FILTER PACK Material	From	To	AMOUNT Sacks or Pounds	METHOD
Bentonite	0	18	13 sacks	overbore

Was drive shoe used? ☒ Y ☐ N Shoe Depth(s) ____
Was drive shoe seal tested? ☒ Y ☐ N How? air

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
6"	+1½	115	.25	steel	☒	☐	☒	☐
5"	115	120	.25	steel	☒	☐	☐	☐
					☐	☐	☐	☐

Length of Headpipe ____ Length of Tailpipe ____

9. PERFORATIONS/SCREENS
☐ Perforations Method ____
☒ Screens Screen Type Johnson

From	To	Slot Size	Number	Diameter	Material	Casing	Liner
115	120	.14	1	5"	stainless	☐	☐
						☐	☐
						☐	☐

10. STATIC WATER LEVEL OR ARTESIAN PRESSURE:
80 ft. below ground Artesian pressure ____ lb.
Depth flow encountered ____ ft. Describe access port or control devices: ____

11. WELL TESTS:
☐ Pump ☐ Bailer ☒ Air ☐ Flowing Artesian

Yield gal./min.	Drawdown	Pumping Level	Time
5			1hr

Water Temp. ____ Bottom hole temp. ____
Water Quality test or comments: ____
____ Depth first Water Encountered ____

12. LITHOLOGIC LOG: (Describe repairs or abandonment)

Bore Dia.	From	To	Remarks: Lithology, Water Quality & Temperature	Water Y	Water N
10"	0	18	Sand with cobbles		x
6"	18	44	Cobbles with gravel		x
6"	44	92	Sand with gravel		x
6"	92	112	Sand fine brown	x	
6"	112	120	Sand course brown	x	

Completed Depth 120 (Measurable)
Date: Started 11-6-97 Completed 11-7-97

13. DRILLER'S CERTIFICATION
I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Firm Name Fogle Pump & Supply, Inc. Firm No 537
Firm Official James M. Fogle Date 11-7-97
and
Supervisor or Operator Todd Fogle Date 11-7-97
(Sign once if Firm Official & Operator)

NESW 10 59N 4W

FORWARD WHITE COPY TO WATER RESOURCES