



IDAHO DEPARTMENT OF WATER RESOURCES WELL DRILLER'S REPORT

Use Typewriter
or
Ball Point Pen

95673

1. DRILLING PERMIT NO. 97-94-N-91
Other IDWR No. _____

2. OWNER:
Name John Austin
Address P.O. Box 2145
City Prichard River State ID Zip 83856

3. LOCATION OF WELL by legal description:

Sketch map location must agree with written location.

N		Twp. <u>56</u> North ☒ or South ☐	
E		Rge. <u>4</u> East ☐ or West ☒	
S		Sec. <u>8</u> SW 1/4 NW 1/4 SW 1/4	
W		Gov't Lot _____ County _____	

Address of Well Site old East Side
OR Bailey RD. City _____
(Give at least name of road & Distance to Road or Landmark)

Lt. _____ Blk. _____ Sub. Name _____

4. PROPOSED USE:

☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other _____

5. TYPE OF WORK

☒ New Well ☐ Modify or Repair ☐ Replacement ☐ Abandonment

6. DRILL METHOD

☐ Mud Rotary ☒ Air Rotary ☐ Cable ☐ Other _____

7. SEALING PROCEDURES

SEAL/FILTER PACK			AMOUNT		METHOD
Material	From	To	Sacks or Pounds		
Bentonite	0	20	9		OVERPACKED

Was drive shoe used? ☒ Y ☐ N Shoe Depth(s) 175
Was drive shoe seal tested? Y ☐ N ☐ How? _____

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
6	172	175	.250	Steel	☒	☐	☐	☐

Length of Headpipe _____ Length of Tailpipe _____

9. PERFORATIONS/SCREENS

☐ Perforations Method N/A
☐ Screens Screen Type _____

From	To	Slot Size	Number	Diameter	Material	Casing	Liner
160	400		160	4"	PVC	☐	☒

10. STATIC WATER LEVEL OR ARTESIAN PRESSURE:

165 ft. below ground Artesian pressure _____ lb.
Depth flow encountered _____ ft. Describe access port or control devices:
SWNWSW 8 56N 4W

11. WELL TESTS:

☐ Pump ☐ Bailor ☒ Air ☐ Flowing Artesian

Yield gal./min.	Drawdown	Pumping Level	Time
5			3 HOURS

Water Temp. _____ Bottom hole temp. _____

Water Quality test or comments: _____

12. LITHOLOGIC LOG: (Describe repairs or abandonment)

Bore Dia.	From	To	Remarks: Lithology, Water Quality & Temperature	Y	N
8	0	3	Top Soil		
8	3	65	SAND		
8	65	172	SANDY CLAY		
8	172	175	Granite		
6	175	177	Weathered Granite	2	
6	177	305	GRANITE		
6	305	306	Fractured Granite	1	
6	306	365	GRANITE		
6	365	366	Fractured GRANITE		
6	366	380	GRANITE		
6	380	383	Fractured Granite	2	
6	383	400	Granite		

RECEIVED

JAN 05 1995

MURLOCK REGION
IDWR

OFFICE USE ONLY

Inspected by TDK

Twp. 56N Rge. 4W Sec. 8

SWNWSW 1/4

MICROFILME

DEC 7 9 1998

AUG 25 1999

Completed Depth 400' (Measurable)
Date: Started 11-22-94 Completed 11-25-94

13. DRILLER'S CERTIFICATION

I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Firm Name Hester Well Drilling Firm No. 528

Firm Official [Signature] Date 11-25-94

and Supervisor or Operator C. Mark Hester Date 11-25-94

(Sign once if Firm Official & Operator)

FORWARD WHITE COPY TO WATER RESOURCES

Identify

Identify from: Tax Parcels

Tax Parcels

AUSTIN, JOHN E & CONCETTA L

Location: 2,286,762.962 1,894,221.070 Meters

Field	Value
ID	15703554
UPDATED	6/17/2023
PIN	RP027750000010A
OWNER	AUSTIN, JOHN E & CONCETTA L
ADDRESS1	114 SANBORN CRK RD
ADDRESS2	
CITY	PRIEST RIVER
STATE	ID
ZIPCODE	83856
P_ADDRESS	114 SANBORN CRK RD
P_ZIPCODE	83856
SUB_NAME	
LEGAL1	8-56N-4W CORNWELL 1ST ADDN LOT 1 & LOT 5 REPLAT 1994 FLEETWOOD 2
LEGAL2	<null>
LEGAL3	<null>
LEGAL4	<null>
LEGAL5	<null>
LEGAL6	<null>
ACRES	8
COUNTY	Bonner
SOURCE	<null>
YEAR_BUILT	<null>
ParcelCount	1
SHAPE	Polygon

Identified 1 feature