RECEIVED

AUG 24 1999

Form 117
11/97

IDAHO DEPARTMENT OF WATER RESOURCES
WELL DRILLER'S REPORT

77200

Office Use Only
Inspected by _____
Twp ____ Rge ____ Sec ____
____ 1/4 ____ 1/4 ____ 1/4
Lat: : : Long: : :

IDWR/North

1. WELL TAG NO. D D0010288
DRILLING PERMIT NO. 97-99N-23
Other IDWR No. _____

POSTED

2. OWNER:
Name Bob Lynch
Address 4824 Gleason-McAbee Road
City Priest River State ID Zip 83856

3. LOCATION OF WELL by legal description:
Sketch map location must agree with written location.

N / W / E / S — x

Twp. 58 North ☒ or South ☐
Rge. 04 East ☐ or West ☒
Sec. 08, ____ 1/4 NW (10 acres) 1/4 NE (40 acres) 1/4 (160 acres)
Gov't Lot ____ County Bonner
Lat: : : Long: : :
Address of Well Site 4824 Gleason-McAbee
City Priest River
(Give at least name of road + Distance to Road or Landmark)

Lt. _____ Blk. _____ Sub. Name _____

4. USE:
☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other _____

5. TYPE OF WORK check all that apply (Replacement etc.)
☒ New Well ☐ Modify ☐ Abandonment ☐ Other _____

6. DRILL METHOD
☒ Air Rotary ☐ Cable ☐ Mud Rotary ☐ Other _____

7. SEALING PROCEDURES

SEAL/FILTER PACK Material	From	To	AMOUNT Sacks or Pounds	METHOD
Bentonite	0	19	3sacks	Overbore

Was drive shoe used? ☒ Y ☐ N Shoe Depth(s) _____
Was drive shoe seal tested? ☐ Y ☐ N How? _____

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
6"	+1	45.10	250	steel	☒	☐	☒	☐
					☐	☐	☐	☐
					☐	☐	☐	☐

Length of Headpipe _____ Length of Tailpipe _____

9. PERFORATIONS/SCREENS
Perforations Method _____
Screens Screen Type Telescoping

From	To	Slot Size	Number	Diameter	Material	Casing	Liner
45	50	20	6"		stainless	☒	☐
						☐	☐
						☐	☐

10. STATIC WATER LEVEL OR ARTESIAN PRESSURE:
16 ft. below ground Artesian pressure ____ lb.
Depth flow encountered 38 ft. Describe access port or control devices: welded well cap

11. WELL TESTS:
☐ Pump ☐ Bailer ☒ Air ☐ Flowing Artesian

Yield gal./min.	Drawdown	Pumping Level	Time
40gpm		50'	1 hr

Water Temp. 50 Bottom hole temp. _____
Water Quality test or comments: clear
Depth first Water Encounter 38'

12. LITHOLOGIC LOG: (Describe repairs or abandonment)

Bore Dia.	From	To	Remarks: Lithology, Water Quality & Temperature	Water Y	Water N
10	0	14	Sand & gravel		x
10	14	19	Clay		x
6	19	38	Clay		x
6	38	50	Sand & gravel	x	

Completed Depth 50' (Measurable)
Date: Started 8-03-99 Completed 8-04-99

13. DRILLER'S CERTIFICATION
I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Company Name Intermountain Drilling Firm No. 513
Firm Official _____ Date 8-17-99
and
Driller or Operator _____ Date 8-17-99
(Sign once if Firm Official & Operator)

58N 4W 8

FORWARD WHITE COPY TO WATER RESOURCES