Form 238-7
6/07

IDAHO DEPARTMENT OF WATER RESOURCES
WELL DRILLER'S REPORT

1. WELL TAG NO. D 0076619
Drilling Permit No. 8857167
Water right or injection well #

2. OWNER:
Name John and Kathy Reynolds
Address 7743 Wishing Well Road
City Las Vegas State NV Zip 89123

3. WELL LOCATION:
Twp. 57 North ☒ or South ☐ Rge. 4 East ☐ or West ☒
Sec. 16 ____ 1/4 (10 acres) NW 1/4 (40 acres) NW 1/4 (160 acres)
Gov't Lot ____ County Bonner
Lat. 48 ° 17.590 (Deg. and Decimal minutes)
Long. 116 ° 50.853 (Deg. and Decimal minutes)
Address of Well Site across from 9540 East River Road
(Give at least name of road + Distance to Road or Landmark) City Priest River
Lot. ____ Blk. ____ Sub. Name

4. USE:
☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation ☐ Thermal ☐ Injection
☐ Other

5. TYPE OF WORK:
☒ New well ☐ Replacement well ☐ Modify existing well
☐ Abandonment ☐ Other

6. DRILL METHOD:
☒ Air Rotary ☐ Mud Rotary ☐ Cable ☐ Other

7. SEALING PROCEDURES:

Seal material	From (ft)	To (ft)	Quantity (lbs or ft³)	Placement method/procedure
bentonite	0	38	1150	pour

8. CASING/LINER:

Diameter (nominal)	From (ft)	To (ft)	Gauge/ Schedule	Material	Casing	Liner	Threaded	Welded
6"	+2	112	250	steel	☒	☐	☐	☒
					☐	☐	☐	☐
					☐	☐	☐	☐
					☐	☐	☐	☐

Was drive shoe used? ☒ Y ☐ N Shoe Depth(s) 112'

9. PERFORATIONS/SCREENS:
Perforations ☐ Y ☒ N Method
Manufactured screen ☒ Y ☐ N Type stainless
Method of installation hammer back

From (ft)	To (ft)	Slot size	Number/ft	Diameter (nominal)	Material	Gauge or Schedule
122	112	20	10	5"	SS	304

Length of Headpipe 2' Length of Tailpipe
Packer ☒ Y ☐ N Type K- packer

10. FILTER PACK:

Filter Material	From (ft)	To (ft)	Quantity (lbs or ft³)	Placement method
N/A				

11. FLOWING ARTESIAN:
Flowing Artesian? ☐ Y ☒ N Artesian Pressure (PSIG)
Describe control device

12. STATIC WATER LEVEL and WELL TESTS:
Depth first water encountered (ft) ____ Static water level (ft) 15
Water temp. (°F) cold Bottom hole temp. (°F)
Describe access port welded plate

Well test:

Drawdown (feet)	Discharge or yield (gpm)	Test duration (minutes)
	10+	2 hours

Test method:

Pump	Bailer	Air	Flowing artesian
☐	☒	☐	☐
☐	☐	☐	☐

Water quality test or comments: good

13. LITHOLOGIC LOG and/or repairs or abandonment:

Bore Dia. (in)	From (ft)	To (ft)	Remarks, lithology or description of repairs or abandonment, water temp.	Water Y	Water N
10	0	20	brown silt and sand		X
10	20	40	blue clay		X
6	40	55	brown silt some course sand		X
6	55	58	blue clay layer		X
6	58	95	brown silt	X	
6	95	122	course sand gravel	X	

RECEIVED
JUN 04 2018
IDWR / NORTH

Completed Depth (Measurable):
Date Started: 04/30/2018 Date Completed: 05/10/2018

14. DRILLER'S CERTIFICATION:
I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Company Name Pioneer Well Drilling Co. No. 725
*Principal Driller [signature] Date 5.10.2018
*Driller [signature] Date 5.10.2018
*Operator I Date
Operator i Date

*** Signature of Principal Driller and rig operator are required.**