Form 238-7
11/97 JGE

IDAHO DEPARTMENT OF WATER RESOURCES
WELL DRILLER'S REPORT

790326

Office Use Only
Inspected by
Twp ____ Rge ____ Sec ____
____ 1/4 ____ 1/4 ____ 1/4
Lat: : : Long: : :

1. WELL TAG NO. D 0029034
DRILLING PERMIT NO.
Other IDWR No.

2. OWNER:
Name Bond Campbell
Address 1150 E Ustick
City Meridian State ID Zip 83642

3. LOCATION OF WELL by legal description:
Sketch map location must agree with written location.

N / W / E / S

Twp. 5 North [X] or South [ ]
Rge. 1 East [ ] or West [X]
Sec. 8 ____ 1/4 (10 acres) NW 1/4 (40 acres) NE 1/4 (160 acres)
Gov't Lot ____ County Ada
Lat: Long:
Address of Well Site 12069 Hwy 16
(Give at least name of road + Distance to Road or Landmark) City Eagle
Lt. ____ Blk. ____ Sub. Name ____

4. USE:
[X] Domestic [ ] Municipal [ ] Monitor [ ] Irrigation
[ ] Thermal [ ] Injection [ ] Other

5. TYPE OF WORK: check all that apply (Replacement etc.)
[X] New Well [ ] Modify [ ] Abandonment [ ] Other

6. DRILL METHOD:
[X] Air Rotary [ ] Cable [ ] Mud Rotary [ ] Other

7. SEALING PROCEDURES:

Seal/Filter Pack Material	From	To	AMOUNT Sacks or Pounds	METHOD
Bentonite	0	200	1000 lbs	overbore

Was drive shoe used? [X] Y [ ] N Shoe Depth(s) 478
Was drive shoe seal tested? [ ] Y [X] N How?

8. CASING/LINER:

Diameter	From	To	Guage	Material	Casing	Liner	Welded	Threaded
6	+2	478	.250	steel	[X]	[ ]	[X]	[ ]
					[ ]	[ ]	[ ]	[ ]
					[ ]	[ ]	[ ]	[ ]

Length of Headpipe ____ Length of Tailpipe ____

9. PERFORATIONS/SCREENS:
[ ] Perforations Method
[ ] Screens Screen Type

From	To	Slot Size	Number	Diameter	Material	Casing	Liner
						[ ]	[ ]
						[ ]	[ ]
						[ ]	[ ]

10. STATIC WATER LEVEL OR ARTESIAN PRESSURE:
380 ft. below ground Artesian pressure ____ lb.
Depth flow encountered 478-503 ft. Describe access port or control devices: cap

11. WELL TESTS:
[ ] Pump [ ] Bailer [X] Air [ ] Flowing Artesian

Yield gal./min.	Drawdown	Pumping Level	Time
40	140	478	4 hr

Water Temp. 90 Bottom hole temp. 90
Water Quality test or comments:
Depth first Water Encounter 300

12. LITHOLOGIC LOG: (Describe repairs or abandonment)

Bore Dia.	From	To	Remarks: Lithology, Water Quality & Temperature	Water Y	Water N
10	0	4	TOP SOIL		
10	4	7	HARD PAN		
10	7	40	SAND AND ROCKS		
8	40	292	SAND W/CLAY STRIPS		
6	292	398	COURSE SAND	X	
6	398	400	CLAY		
6	400		COURSE SAND-DECOMPOSED		
		503	GRANIT	X	

RECEIVED
MAR 05 2003
WATER RESOURCES
WESTERN REGION

Completed Depth 503 (Measurable)
Date: Started 2/5/1~~9~~3 2003 Completed 2/10/2003

13. DRILLER'S CERTIFICATION:
I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Company Name Treasure Valley Drilling Firm No. 560
Firm Official and Date 2/20/2003
Driller or Operator Date 2/20/2003
(Sign once if Firm Official & Operator)

SCANNED
OCT 05 2023