

96025

Form 238-7
3/95-C96IDAHO DEPARTMENT OF WATER RESOURCES
WELL DRILLER'S REPORT

Office Use Only			
Inspected by			
Twp	Rge	Sec	
1/4	1/4	1/4	
Lat:	Long:		

1. DRILLING PERMIT NO. 65-99-W-0137-000
 Other IDWR No. D0009667
2. OWNER:
 Name Janis Carr
 Address 1190 N Locust Grove
 City Meridian State ID Zip 83642
3. LOCATION OF WELL by legal description:
 Sketch map location must agree with written location
N

W		E	Twp. <u>10</u> North ☒ or South ☐
			Rge. <u>1</u> East ☒ or West ☐
			Sec. <u>25</u> 1/4 NW 1/4 NE 1/4

Gov't lot _____ County Gem

Lat: _____ Long: _____

 Address of Well Site 21850 Main St
 Ola General Store City Ola
 (Give at least name of road + Distance to Road or Landmark)

Lt. _____ Blk. _____ Sub. Name _____

4. USE:
☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☒ Other public water supply
5. TYPE OF WORK check all that apply (Replacement etc.)☒ New Well ☐ Modify ☐ Abandonment ☐ Other _____**6. DRILL METHOD**☒ Air Rotary ☐ Cable ☐ Mud Rotary ☐ Other _____**7. SEALING PROCEDURES**

SEAL/FILTER PACK		AMOUNT		METHOD
Material	From	To	Sacks or Pounds	
Bentonite	2'	40'	30	overbore

Was drive shoe used? ☒ Y ☐ N Shoe Depth(s) _____Was drive shoe seal tested? ☐ Y ☒ N How? _____**8. CASING/LINER:**

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
6"	+2'	57"	250	Steel	☒	☐	☒	☐
4.5"	41'	121'	Se40	PVC	☐	☒	☐	☐

Length of Headpipe _____ Length of Tailpipe _____

9. PERFORATIONS/SCREENS
☒ Perforations Method saw
☐ Screens Screen Type _____

From	To	Slot Size	Number	Diameter	Material	Casing	Liner
61'	81'		150	4.5"	PVC	☐	☒
101'	121'		150	4.5"	PVC	☐	☒

10. STATIC WATER LEVEL OR ARTESIAN PRESSURE:
 30ft. below ground Artesian Pressure _____ lb
 Depth flow encountered _____ ft. Describe access port or control devices: _____
11. WELL TESTS:☐ Pump ☐ Bailer ☒ Air ☐ Flowing Artesian

Yield gal/min	Drawdown	Pumping Level	Time
6	80	110	2 hrs

Water Temp. _____ Bottom hole temp. _____

Water Quality test or comments: _____

Depth first Water Encountered 16'**12. LITHOLOGIC LOG: (Describe repairs or abandonment)**

Bore Dia	From	To	Remarks: Lithology, Water Quality & Temp.	Water	
				Y	N
12"	0'	4'	hard brown clay		☒
12"	4'	16'	sandy brown clay		☒
12"	16'	21'	gravel & broken rock/boulders	☒	
12"	21'	24'	soft sandy clay		☒
12"	24'	42'	dark brown clay		☒
6"	42'	51'	dark brown clay		☒
6"	51'	57'	light blue clay		☒
6"	57'	59'	blue clay		☒
6"	59'	60'	pack quartz sand	☒	
6"	60'	85'	blue clay		☒
6"	85'	90'	blue clay w/cracks	☒	
6"	90'	112'	dark blue clay		☒
6"	112'	118'	dark blue clay w/cracks	☒	
6"	118'	122'	dark blue clay		☒

RECEIVED

JUN 21 1999

WATER RESOURCES
WESTERN REGION

RECEIVED

MICROFILMED

JUN 23 1999

AUG 25 1999

Department of Water Resources

Completed Depth: 121 (Measurable)Date: Started 6-14-99 Completed 6-15-99**13. DRILLER'S CERTIFICATION**

I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Firm Name SOS Welldrilling & Pump CoFirm No. 212

Firm Official _____

Date 6-18-99

Supervisor or Operator _____

(Sign once if Firm Official & Operator)

Date 6-18-99

Date: 06/17/99 Time: 4:59 PM