

IDAHO DEPARTMENT OF WATER RESOURCES
WELL DRILLER'S REPORT

Office Use Only			
Well ID No.	803260		
Inspected by			
Twp	Rge	Sec	
	1/4	1/4	1/4
Lat:	:	Long:	:

1. WELL TAG NO. D 00 29340
DRILLING PERMIT NO. _____
Water Right or Injection Well No. _____

2. OWNER:
Name Jack + A-Tis Quinny
Address Box 20 Hi Valley Rd
City ola State ID Zip 83657

3. LOCATION OF WELL by legal description:

You must provide address or Lot, Blk, Sub. or Directions to well.

Twp. 10 North ☒ or South ☐
Rge. 1 East ☒ or West ☐
Sec. 24 1/4 NW 1/4 NE 1/4
Gov't Lot _____ County Gems

Lat: _____ Long: _____
Address of Well Site 15 House on RT on Hi Valley Road City _____
(Give at least name of road + Distance to Road or Landmark)
Lt. 1 Blk. 1 Sub. Name _____

4. USE:

☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other _____

5. TYPE OF WORK check all that apply (Replacement etc.)

☒ New Well ☐ Modify ☐ Abandonment ☐ Other _____

6. DRILL METHOD:

☒ Air Rotary ☐ Cable ☐ Mud Rotary ☐ Other _____

7. SEALING PROCEDURES

Seal Material	From	To	Weight / Volume	Seal Placement Method
<u>Pontomite</u>	<u>0</u>	<u>38</u>	<u>11</u>	<u>Granular</u>

Was drive shoe used? ☐ Y ☒ N Shoe Depth(s) _____
Was drive shoe seal tested? ☐ Y ☐ N How? _____

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
<u>6"</u>	<u>+ 2</u>	<u>38</u>	<u>250</u>	<u>Steel</u>	☒	☐	☒	☐
<u>4"</u>	<u>- 36</u>	<u>260</u>	<u>160</u>	<u>PVC</u>	☐	☒	☐	☒

Length of Headpipe _____ Length of Tailpipe _____
Packer ☐ Y ☐ N Type _____

9. PERFORATIONS/SCREENS PACKER TYPE

Perforation Method Factory
Screen Type & Method of Installation PVC

From	To	Slot Size	Number	Diameter	Material	Casing	Liner
<u>200</u>	<u>260</u>	<u>25</u>	<u>160</u>	<u>4"</u>	<u>PVC</u>	☐	☒

10. FILTER PACK

Filter Material	From	To	Weight / Volume	Placement Method
	<u>15</u>	<u>38</u>		

11. STATIC WATER LEVEL OR ARTESIAN PRESSURE:

45 ft. below ground Artesian pressure _____ ft.
Depth flow encountered 30-260 ft. Describe access port or control devices: Turtle Cap

12. WELL TESTS:

☐ Pump ☐ Bailor ☒ Air ☐ Flowing Artesian

Yield gal./min.	Drawdown	Pumping Level	Time
<u>14</u>	<u>260</u>	<u>260</u>	

Water Temp. 60° Bottom hole temp _____
Water Quality test or comments: Clean + Clear Slightly Cloudy
Depth first Water Encounter 180

13. LITHOLOGIC LOG: (Describe repairs or abandonment)

Bore Dia.	From	To	Remarks: Lithology, Water Quality & Temperature	Water	Y	N
<u>10</u>	<u>0</u>	<u>18</u>	<u>Brown Clay</u>			
<u>8</u>	<u>13</u>	<u>30</u>	<u>Brown soft granite</u>			
<u>8</u>	<u>30</u>	<u>39</u>	<u>Hard Brown-grey</u>			
<u>6</u>	<u>39</u>	<u>70</u>	<u>Sandy blue clay</u>			
	<u>70</u>	<u>180</u>	<u>White granite</u>			
	<u>180</u>	<u>260</u>	<u>Grey-Brown granite</u>			
	<u>260</u>	<u>270</u>	<u>sandy blue clay caves</u>			

RECEIVED

OCT 20 2003

WATER RESOURCES
WESTERN REGION

Completed Depth 260 (Measurable)
Date: Started 6-5-03 Completed 6-9-03

14. DRILLER'S CERTIFICATION

I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Company Name Jim's Drywall Firm No. 623
Principal Driller [Signature] Date 6-9-03
and _____
Driller or Operator II _____ Date _____
Operator I _____ Date _____

Principal Driller and Rig Operator Required.
Operator I must have signature of Driller/Operator II.