

IDAHO DEPARTMENT OF WATER RESOURCES
WELL DRILLER'S REPORT

835012
Office Use Only
Well ID No. 405535
Inspected by _____
Twp _____ Rge _____ Sec _____
1/4 _____ 1/4 _____ 1/4 _____
Lat: _____ Long: _____

1. WELL TAG NO. D 0039410

DRILLING PERMIT NO. _____

Water Right or Injection Well No. _____

2. OWNER:

Name Ross Meade

Address 19966 Lower Pleasant Ridge Road

City Caldwell State Id Zip 83607

3. LOCATION OF WELL by legal description:

You must provide address or Lot, Blk, Sub. or Directions to well.

Twp. 04 North ☒ or South ☐

Rge. 04 East ☐ or West ☒

Sec. 23 1/4 SW 1/4 SW 1/4

Gov't Lot _____ County Canyon

Lat: _____ Long: _____

Address of Well Site Same as above

City _____

(Give at least name of road + Distance to Road or Landmark)

Lt. _____ Blk. _____ Sub. Name _____

4. USE:

☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other _____

5. TYPE OF WORK check all that apply

(Replacement etc.)

☒ New Well ☐ Modify ☐ Abandonment ☐ Other _____

6. DRILL METHOD:

☐ Air Rotary ☒ Cable ☐ Mud Rotary ☐ Other _____

7. SEALING PROCEDURES

Seal Material	From	To	Weight / Volume	Seal Placement Method
Perma Plug				Placed dry in
Bentonite	1	20	350#	annular space

Was drive shoe used? ☒ Y ☐ N Shoe Depth(s) 403

Was drive shoe seal tested? ☒ Y ☐ N How? Bailed down

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
6"	2'3"	403	.25	Steel	☒	☐	☒	☐
					☐	☐	☐	☐
					☐	☐	☐	☐

Length of Headpipe _____ Length of Tailpipe _____

Packer ☐ Y ☐ N Type _____

9. PERFORATIONS/SCREENS PACKER TYPE

Perforation Method _____

Screen Type & Method of Installation _____

From	To	Slot Size	Number	Diameter	Material	Casing	Liner
						☐	☐
						☐	☐
						☐	☐

10. FILTER PACK

Filter Material	From	To	Weight / Volume	Placement Method

11. STATIC WATER LEVEL OR ARTESIAN PRESSURE:

_____ ft. below ground Artesian pressure 12 lb.

Depth flow encountered _____ ft. Describe access port or control devices: _____

Values on top of Flange Cap & Pressure Gauge

12. WELL TESTS:

☐ Pump ☐ Bailor ☒ Air ☒ Flowing Artesian

Yield gal./min.	Drawdown	Pumping Level	Time
60	10	10	5
60	0	+ 1	20

Water Temp. 77 Bottom hole temp. _____

Water Quality test or comments: 5 grains slight odor some iron Depth first Water Encounter 20

13. LITHOLOGIC LOG: (Describe repairs or abandonment)

Water

Bore Dia.	From	To	Remarks: Lithology, Water Quality & Temperature	Y	N
10	0	2	Soil		X
10	2	14	Brown Clay		X
10	14	16	Brown Sand		X
10	16	20	Brown Clay		X
6	20	45	Brown Sand & Gravel	X	
6	45	58	Brown Clay		X
6	58	60	Brown Sand	X	
6	60	66	Brown Clay		X
6	66	75	Blue Clay		X
6	75	75	Black Sand	X	
6	75	118	Blue Clay		X
6	118	119	Black Sand	X	
6	119	130	Blue Clay		X
6	130	206	Blue Black Clay		X
6	206	213	Blue Soft Sand Stone	X	
6	213	218	Blue Clay		X
6	218	221	Black & White Sand	X	
6	221	232	Blue Clay		X
6	232	257	Black Fine Sand	X	
6	257	463	Blue Clay		X
6	463	?	Black Sand	X	

RECEIVED

AUG 19 2005

WATER RESOURCES
WESTERN REGION

Completed Depth 462' (Measurable)

Date: Started 26 July 2005 Completed 10 Aug 05

14. DRILLER'S CERTIFICATION

I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Gary Duspiva Well
Company Name Drilling & Development Firm No. 395

Principal Driller Gary Duspiva Date 18 Aug 05

and Driller or Operator II _____ Date _____

Operator I Ante Duspiva Date 18 Aug 05

Principal Driller and Rig Operator Required.

Operator I must have signature of Driller/Operator II.

FORWARD WHITE COPY TO WATER RESOURCES