

RECEIVED

APR 6 2000

Department of Water Resources

BIG TIMBER CREEK DIVERSIONS PHOTO LOG

PHOTO 1: KERMIT PUCELL DIVERSION NO LOCKING CONTROL, FOUR FOOT CIPOLETTI NEEDS RESET AND METAL EDGE. GPS TAG: A0003089 FILE: R103025A

PHOTO 2: ALLAN PURCELL DIVERSION NO LOCKING CONTROL OR MEASURING DEVICE. GPS TAG: A0003090 FILE: R103015B

PHOTO 3 & 4: KERMIT PURCELL DIVERSION NO LOCKING CONTROL, FOUR FOOT CIPOLETTI NEEDS RESET AND METAL EDGE. GPS TAG: A0003091 FILE: R103016A

PHOTO 5 & 6: RICHARD FOSTER DIVERSION NO LOCKING CONTROL, FOUR FOOT CIPOLETTI NEEDS NEW EDGE AND RESET. GPS TAG: A0003092 FILE: R103016B

PHOTO 7: ALLAN PURCELL DIVERSION NO LOCKING CONTROL, NO MEASURING DEVICE. GPS TAG: A0003093 FILE: R103016C

PHOTO 8 & 9: JAMES WHITTAKER DIVERSION METAL SCREW GATE LOCKABLE, MEASURING DEVICE NEEDS REPLACED. GPS TAG: A0003094 FILE: R103018A

PHOTO 10 & 11: MEMPHI RANCHES DIVERSION CONTROL STRUCTURE LOCKABLE, MEASURING DEVICE NEEDS MINOR MAINTENANCE. GPS TAG: A0003095 FILE: R103018B

PHOTO 12 & 13: JAMES WHITTAKER DIVERSION LOCKABLE METAL SCREW GATE, SIX FOOT CIPOLETTI NEEDS MINOR MAINTENANCE. GPS TAG: A0003096 FILE: R103019A

PHOTO 1 & 2: KURT BIRD DIVERSION NO LOCKABLE CONTROL, SIX FOOT CIPOLETTI IN NEED OF MAJOR REPAIR OR REPLACEMENT. GPS TAG: A0003097 FILE: R103019B

**PHOTO 3 & 4: LEMHI RANCHES DIVERSION NO LOCKABLE
CONTROL, FOUR FOOT CIPOLETTI NEEDS REPLACED. GPS
TAG: A0003098 FILE: R103019C**

**PHOTO 5 & 6: CARL ELLSWORTH DIVERSION LOCKABLE
CONTROL, THREE FOOT CIPOLETTI NEEDS REPLACED AND
MOVED CLOSER TO POINT OF DIVERSION, CURRENTLY
APPROX. 400 YARDS DOWNSTREAM FROM POINT OF
DIVERSION. GPS TAG: A0003099 FILE: R103019D**